



## Stocklist for Amplifier

### Amplifier: For Strain Gauge Sensors

Product Picture	Article Code	Article Number	Description
	IMA2 DMS 24V 0-10V	115865	24V Versorgung  0-10 V Ausgangssignal

### Amplifier: For Potentiometric Sensors

Product Picture	Article Code	Article Number	Description
	MVR 30VDC 0-10V	122049	Supply Voltage 10...30VDC  Output 0-10V