



Stocklist for Amplifier

Amplifier: For Strain Gauge Sensors

Product Picture	Article Code	Article Number	Description
	IMA2 DMS 24V 0-10V	115865	24V Versorgung 0-10 V Ausgangssignal

Amplifier: For Potentiometric Sensors

Product Picture	Article Code	Article Number	Description
	MVR 30VDC 0-10V	122049	Supply Voltage 10...30VDC Output 0-10V