

# HF TYPE A-B-C

## ARC STARTING FOR dc TIG WELDING MACHINE OR PLASMA CUT MACHINE

- Type A : 200 pulses per second 600V TIG
- Type B: 300 pulses per second 800V TIG
- Type C: 400 pulses per second 800V TIG + PLASMA
- The devices requires an external pulse-transformer with winding ratio 1:10 for TIG application and 1:20 for plasma-cut application.

